



## Revision of Precautions

### Patch test products containing gold (I) sodium thiosulfate

July 4, 2017

**Non-proprietary name**

Patch test products containing gold (I) sodium thiosulfate

**Safety measure**

Precautions should be revised in the package insert.

In the Important Precautions section with regard to late positive reactions, the following text should be revised (underlined parts are revised):

Late positive reactions may occur 7 to 10 days after the test. With gold (I) sodium thiosulfate, there have been reports of a late positive reaction occurring as late as 20 days or more after the test.

In the Important Precautions section, the following text should be added (underlined parts are revised):

Before performing the patch test, patients should be informed that sensitization or late positive reactions may occur, and be instructed to visit a medical institution immediately if positive reactions occur after the test result is determined.