



---

*This English version is intended to be a reference material to provide convenience for users. In the event of inconsistency between the Japanese original and this English translation, the former shall prevail.*

# Revision of Precautions

## Patch test products containing gold (I) sodium thiosulfate

July 4, 2017

### Non-proprietary name

Patch test products containing gold (I) sodium thiosulfate

### Safety measure

Precautions should be revised in the package insert.

In the Important Precautions section with regard to late positive reactions, the following text should be revised (underlined parts are revised):

Late positive reactions may occur 7 to 10 days after the test. With gold (I) sodium thiosulfate, there have been reports of a late positive reaction occurring as late as 20 days or more after the test.

In the Important Precautions section, the following text should be added (underlined parts are revised):

Before performing the patch test, patients should be informed that sensitization or late positive reactions may occur, and be instructed to visit a medical institution immediately if positive reactions occur after the test result is determined.